LOCAL NOTICE TO MARINERS

U.S. Department of Transportation

United States Coast Guard



WEEKLY SUPPLEMENT

ISSUED BY: COMMANDER ELEVENTH COAST GUARD DISTRICT (POW)

Coast Guard Island, Building 50-6, Alameda, California 94501-5100

Telephone: Day: (510) 437-2976 24 Hour FAX: (510)437-5836

For subscription information and other questions, comments and suggestions, call (510) 437-2976.

Boating Safety Classes or Information: 1-800-869-SAIL (7245)

** Electronic Bulletin Board Service: (703) 313-5910 **

300 to 28.8bps, 8 data bits, no parity, 1 stop bit

** NIS watchstander, 24 hours a day at (703) 313-5900 **

** INTERNET ADDRESS **

HTTP://www.navcen.uscg.mil

OR

FTP://ftp.navcen.uscg.mil

BROADCAST NOTICE TO MARINERSInformation concerning aids to navigation and waterways management promulgated by BNM 0418/97 to BNM 0428/97 have been incorporated in this notice if still significant.

LIGHT LIST REFERENCE: COMDTPUB P16502.6 LIGHT LIST, VOLUME VI 1996 Edition

USE OF THE LOCAL NOTICE TO MARINERS

With the exceptions of Sections II and III, the Weekly Supplemental editions contain only new information available in the past seven days. For all available information concerning the waterways of the Eleventh Coast Guard District, consult Monthly Edition 19/97, and Weekly Supplements 20/97 & 21/97.

I. SPECIAL NOTICES

OMEGA STATUS AS OF 27 MAY 1997

All Omega Stations are on-air. Omega status recording phone number (703) 313-5906. LNM 22/97 dated 27 May 1997.

LORAN-C STATUS AS OF 27 MAY 1997

Loran-C Stations for 8290/9940 Chains are on air. For information regarding the Loran-C System, contact the Coordinator of Chain Operations West Coast at (707)765-7590. LNM 22/97 dated 27 May 1997.

D-GPS STATUS AS OF 27 MAY 1997

All dGPS sites are on air.
The Point Loma dGPS signal will experience intermittent outage from 0700T on 16 June to 2000T on 17 June 1997.
The Point Arguello dGPS signal will experience intermittent outage from 0700T on 19 June to 2000T on 20 June 1997
The Point BluntdGPS signal will experience intermittent outage from 0700T to 2000T on 23 June 1997 Also, the Point Blunt site is scheduled to be off-airfrom 1000T to 1200T on 09 June 1997
The Pigeon PointdGPS signal will experience intermittent outage from 0700T to 2000T on 22 June 1997 Also, the Pigeon Point site is scheduled to be off-airfrom 1000T to 1200T on 02 June 1997 For information regarding the dGPS system, or for status updates contact the Petaluma Control Center at (707)765-7612/7613.
LNM 22/97 dated 27 May 1997.

II. <u>DISCREPANCIES</u>/ <u>DISCREPANCIES CORRECTED</u>

DISCREPANCIES: (bold type and * denote new information since last LNM)

LLNR	NAME OF AID	STATUS	CHARTS AFFECTED	BNM REF.	LNM <u>REF.</u>	
				· <u></u>	·	
5.00	POINT LOMA LIGHT	RED INTENSITY/OBSCURED	18740	0043-95	46/95	
177.00	NOAA ENVIRONMENTAL LB EB 46045	EXTINGUISHED	18740	0198-97	10/97	
1605.00	SHELTER ISLAND YACHT BASIN BUOY 7	OFF STATION	18773	0243-97	13/97	
2770.00	ANAHEIM BAY ENTRANCE LBB1	OFF STATION	18749	0423-97	22/97*	
4235.00	BONITA CHANNEL LIGHTED BELL BUOY 3	MISSING	18649	0410-97	22/97*	
4275.00	HORSESHOE BAY E BREAKWATER LT	EXTINGUISHED	18649	N/A	15/97	
4302.00	SAN FRANCISCO WEST YACHT HBR LB 3	MISSING	18649	N/A	06/97	
4780.00	BALLENA BAY LIGHT 1	IMPROPER CHARACTERISTIC	18649	0285-97	16/97	
5790.00	MOLATE POINT WHARF SOUTH END LT	EXTINGUISHED/FOG SIGNAL INOP	18649	0007-97	02/97	

Discrepancy Information (cont'd)

6280.00 7920.00 8420.00 8445.00 8450.00 8500.00 8515.00 8520.00	AMORCO WHARF LIGHTS (2) BODEGA BAY DAYBEACON 29 LAKE TAHOE BUOY 6 LAKE TAHOE BUOY 16 LAKE TAHOE BUOY 18 LAKE TAHOE BUOY 32 LAKE TAHOE BUOY 38 LAKE TAHOE BUOY 40	EXTINGUISHED DAMAGED OFF STATION MISSING MISSING MISSING MISSING MISSING	18656 18643 18665 18665 18665 18665 18665	0344-97 0286-97 N/A N/A N/A N/A N/A N/A	18/97 17/97 15/97 15/97 16/97 15/97 15/97				
DISCREPANCIES CORRECTED:									
510.00 3290.00 7240.00 7555.00	NOAA ENVIRONMENTAL LB EB 46006 CABRILLO BEACH LAUNCH RAMP NORTH LT SACRAMENTO RIVER DWSC LT 16 SACRAMENTO RIVER DWSC LT 74	WATCHING PROPERLY RELIGHTED RELIGHTED RELIGHTED	18620 18751 18661 18662	0372-94 0696-96 0251-97 0255-97	18/94 39/96 14/97 14/97				

III. TEMPORARY CHANGESTEMPORARY CHANGES CORRECTED - ESTABLISHED/DISCONTINUED AIDS

TEMPORARY	TEMPORARY CHANGES: (bold type and * denote new information since last LNM)				LNM
<u>LLNR</u>	NAME OF AID	<u>STATUS</u>	<u>AFFECTED</u>	REF.	REF.
0.00	SAUSALITO CHANNEL LIGHTED BUOY WR1	TEMPORARILY ESTABLISHED	18649	0798-96	43/96
2470.00	NEWPORT BAY CHANNEL LIGHT 11	TRLB	18754	0597-95	24/95
3221.00	RESERVATION POINT NORTH BUOY	TEMPORARILY DISCONTINUED	18751	N/A	29/96
3222.00	RESERVATION POINT MIDDLE BUOY	TEMPORARILY DISCONTINUED	18751	N/A	29/96
3223.00	RESERVATION POINT SOUTH BUOY	TEMPORARILY DISCONTINUED	18751	N/A	29/96
5995.00	PETALUMA RIVER ENTRANCE CHAN DBN 5	TRUB	18654	N/A	22/97*
8035.00	TOMALES BAY BUOY 3	TRUB	18643	0247-97	14/97

TEMPORARY CHANGES CORRECTED:

None.

IV. CHART CORRECTIONS See LNM 19/97 for explanation of format.)

501 9th ed., 10/10/92 LAST LNM 11/97 NAD 83

North America, West Coast - Mexican Border to Dixon Entrance
Relocate NOAA Environmental Lighted Buoy 46006, Fl (4) Y 20s ODAS

from (40°48'42"N, 137°39'00"W) to 40°51'00.0"N 137°31'00.0"W

V. ADVANCE NOTICE OF CHANGES IN AIDS TO NAVIGATION

SOUTHERN CALIFORNIA - LOS ANGELES HARBORAID ESTABLISHMENT - The U.S. Coast Guard will establish a range in Los Angeles Main Channel in June 1997. The range will mark the centerline of the realigned channel due to the Pier 400 dredging and landfill project. The Front Light will be established in position 3343'09.6"N, 118°16'17.1"W with a fixed yellow light. The Rear Light will be established in position 343'10.9"N, 118°16'20.0"W with a 6 second isophase yellow light. Comments may be directed to CommandeP(w), Coast Guard Island, Bldg. 50-6, Alameda CA 94501-5100Attn: LCDR Anne Burkhardt, or call (510)437-2978.

Charts: 18749, 18751 LNM 10/97 dated 04 March 1997

VI. PROPOSED CHANGES IN AIDS TO NAVIGATION

SOUTHERN CALIFORNIA - SANTA BARBARA HARBORID DISCONTINUANCE - Due to significant input from the local mariners, the U. S. Coast Guard will not discontinue Santa Barbara Light (LLNR 195) at this time. Comments may be directed to Commander (w), Coast Guard Island, Bldg. 50-6, Alameda CA 94501-5100,Attn: LTjg Dave Husted, or call (510)437-2969. Charts: 18720, 18725 LNM 21/97 dated 20 May 1997

VII. GENERAL INFORMATION

SOUTHERN CALIFORNIA - SAN DIEGO BAYDREDGING OPERATIONS - Soli-Flo will be conducting dredging operations at hollas Creek in San Diego Bay **from 01 June to 31 July 1997.** The Dredge *EXSILTATION* will be onscene and will monitor Channels 16 and 80 VHF-FM. Two dump scows, a tug, and a workboat will also be used.

Chart: 18773 LNM 22/97 dated 27 May 1997

SOUTHERN CALIFORNIA - LOS ANGELES HARBORER RESTORATION - John Meek Company will be conducting pier restoration at the abrillo Fishing Pier **through October 1997**. Pier work will be conducted with work rafts and scaffolding. For the safety of the workers, mariners are requested to transit the area so as not to produce a wake.

Chart: 18751 LNM 22/97 dated 27 May 1997

BRIDGE INFORMATION - DISCREPANCIES AND CORRECTIONS -

Questions regarding bridge operations, regulations or permit applications, please contact: Eleventh Coast Guard District Bridge Section, Coast Guard Island, Building 50-6, Alameda, CA 94501-5100 Phone: (510) 437-3514.

SOUTHERN CALIFORNIA - CERRITOS CHANNEL - FORD (BADGER AVENUE) BRIDGE 150-day bridge closure began05 May 1997, and will continue until 02 October 1997 The Coast Guard published a special operating regulation for this closure in the Federal Register on 20 Nov 1996. Additionally, the Coast Guard Captain of the Port Los Angeles/Long Beach has established a safety zone at the bridge prohibiting vessels from entering the work area or transiting the bridge. This safety zone will remain in effect until the new bridge is in operation. Chart: 18751

NORTHERN CALIFORNIA - SAN FRANCISCO BAY - DUMBARTON HIGHWAY BRIDGE green light marking the center of the navigation channel on the north side of the bridge is extinguished.

Charts: 18651, 18652

NORTHERN CALIFORNIA - SAN FRANCISCO BAY - OAKLAND INNER HARBOR - FRUITVALE AVENUE HIGHWAY BRIDTONE bridge will be unable to open for vessel traffic during sidewalk plating replacement for four 6-hour periods. Anticipated closure times and dates 40900T-1500T, 03-04 June 1997, and again from 0900T-1500T, 10-11 June 1997 Clearance under the closed bridge is 13 ft. above Mean High Water. Charts: 18649, 18650, 18652

NORTHERN CALIFORNIA - SAN FRANCISCO BAY - OAKLAND INNER HARBOR - PARK STREET BRIDGES 8 ft. by 38 ft. spudded barge is moored at the Alameda Island side for the Park Street Bridge painting project. The barge will be lighted and marked at night. Scaffolding will run the length of the Alameda leaf, and will reduce vertical clearance by 3 feet. The inoperable leaf will be flagged with fixed red lights placed every 25 feet. In addition skimmers, circling the barge, will extend 10 feet beyond the Alameda leaf, and will have yellow flashing lights. Horizontal clearances with only the Oakland leaf operable is 83 ft. Work hours will be0700T-1900T daily Charts: 18649, 18650, 18652

NORTHERN CALIFORNIA - SAN FRANCISCO BAY - SAN LEANDRO BAY - BAYFARM ISLAND BICYCLE AND HIGHWAY BRIDGESsure to replace the bridge gear is anticipated from 0900T-1200T during the first week of June 1997Clearance under the closed bridge is 20 ft. above MHW. Charts: 18649, 18650, 18652

NORTHERN CALIFORNIA - SAN FRANCISCO BAY-SAN PABLO BAY - NAPA RIVER - BRAZOS BRID@ Eler repair will commence in June 1997, and will continue until November 1997. A barge will reduce the horizontal clearance past the bridge to approximately 115 ft. The barge will be lighted and marked, and removed from the navigable channel at night. Charts: 18652, 18654

NORTHERN CALIFORNIA - SAN FRANCISCO BAY - NAPA RIVER-MARE ISLAND CAUSEWAApairs and inspection have been completed. Chart: 18652, 18654, 18655

NORTHERN CALIFORNIA - SACRAMENTO RIVER DELTA STEAMBOAT SLOUGH- GRAND ISLAND BASCULE BRIDGET rans seismic retrofit will continue untilmid-June 1997 Work has concluded at the south leaf, and is now being performed on the north leaf, which is flagged with red lights placed every 30 ft. Horizontal clearance at the waterline with one leaf in service is 100 feet. Vertical clearance past the inoperable leaf is 21 ft. above Mean High Water, and 24 ft. above Mean Lower Low Water. Chart: 18662

NORTHERN CALIFORNIA - SACRAMENTO RIVER - "I" STREET UPRR BRIDGE IN SACRAMENT@moval of logs and other debris at the bridge has been completed.

Chart: 18662

NORTHERN CALIFORNIA - HUMBOLDT BAY - EUREKA SLOUGH - U.S. 101 BRID 656 Trans is painting the bridge. Vertical clearance under the bridge is reduced by 7 feet. A barge will also reduce the horizontal clearance by 20 feet during the daytime. Work will conclude 20/June 1997. Chart: 18622

CORRECTIONS TO LIGHT LIST, VOLUME VI; PACIFIC COAST AND PACIFIC ISLANDS 19 96: (*Denotes the column in which a correction has been made or new information added.)

(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	
No.	Name and location	Position	Characteristic	Height	Range	Structure	Remarks	
			CALIF	ORNIA - E	Eleventh D	istrict		
510	NOAA Environmental Lighted Buoy EB 46006	40 51.0 137 31.0	FI (4) Y 20s			Yellow disk-sha buoy.	ped	22/97

IX. ADDITIONAL ENCLOSURES

None.

M. L. VANHOUTEN Chief, Aids to Navigation Section Waterways Management Branch Eleventh Coast Guard District